

East Texas Ag Services

Photo Log

Description: View of smoldering facility and piles of fertilizer materials.


Category: Site Photo

Latitude:

Date Taken: 5/30/2014

Longitude:

Tags:



Description: View of smoke from fire (looking north).

Category: Site Photo

Latitude:

Date Taken: 4/30/2014

Longitude:

Tags:



Description: View from south of fertilizer piles in facility.


Category: Site Photo

Latitude: 32.22241944444444

Date Taken: 5/30/2014

Longitude: -95.84616944444444

Tags:



Description: A back hoe was used to knock down the cinderblock walls of the facility in order to contain the fire.

Category: Site Photo

Latitude: 32.20603055555556

Date Taken: 5/30/2014

Longitude: -95.85571388888889

Tags:



Description: Response crews stand back and assess the fire from the south on the morning of 30 May 2014.

Category: Site Photo

Latitude:

Date Taken: 6/30/2014

Longitude:

Tags:



East Texas Ag Services

Photo Log

Description: Athens Fire Department suppressing fire on morning of 30 May 2014

Category: Site Photo

Latitude:

Date Taken: 5/30/2014

Longitude:

Tags:



Description: View of facility after fire was extinguished.

Category: Site Photo

Latitude:

Date Taken: 5/30/2014

Longitude:

Tags:



Description: View of containment berm along northern edge of facility to prevent migration of firefighting water.

Category: Site Photo

Latitude:

Date Taken: 5/30/2014

Longitude:

Tags:



Description: View of facility following fire.

Category: Site Photo

Latitude: 32.2062638888889

Date Taken: 5/30/2014

Longitude: -95.8555222222222

Tags:



East Texas Ag Services

Photo Log

Description: View of bermed liquids in northern area of facility. EPA collected sample of liquid. Results are pending. TCEQ subcontractor recovered liquids and staged in on-site frac-tank.

Category: Site Photo

Latitude: 32.206475

Date Taken: 5/30/2014

Longitude: -95.85568333333333

Tags:



Description: View of ponded liquids adjacent to facility and railroad tracks. Recovered liquid is staged in on-site frac-tank.

Category: Site Photo

Latitude: 32.20625555555556

Date Taken: 5/30/2014

Longitude: -95.85534722222222

Tags:



Description: View of ponded area following recovery of liquids.

Category: Site Photo

Latitude: 32.20630277777778

Date Taken: 5/30/2014

Longitude: -95.85528611111111

Tags:

